

螺栓规格表

		
六角尺寸 S(mm)	螺纹尺寸 D(mm)	六角尺寸 J(mm)
17	M10	8
19	M12	10
22	M14	12
24	M16	14
27	M18	14
30	M20	17
34	M22	17
36	M24	19
41	M27	19
46	M30	22
50	M33	24
55	M36	27
60	M39	27(30)
65	M42	32
70	M45	—
75	M48	36
80	M52	36
85	M56	41
90	M60	46
95	M64	50
100	M68	55
105	M72	60
110	M76	65
115	M80	70
120	M85	70(75)
130	M90	—
135	M95	85
145	M100	—
150	M105	—
155	M110	—
165	M115	—
170	M120	—
180	M125	—
185	M130	—
200	M140	—
210	M150	—

		
六角尺寸 S(英寸)	螺纹尺寸 D(英寸)	六角尺寸 J(英寸)
1-1/16	5/8	1/2
1-1/4	3/4	5/8
1-7/16	7/8	3/4
1-5/8	1	3/4
1-13/16	1-1/8	7/8
2	1-1/4	7/8
2-3/16	1-3/8	1
2-3/8	1-1/2	1
2-9/16	1-5/8	—
2-3/4	13/4	1-1/4
2-15/16	1-7/8	1-3/8
3	2	1-1/2
3-1/8	2	1-5/8
3-3/8	2-1/4	1-3/4
3-1/2	2-1/4	1-3/4
3-3/4	2-1/2	1-3/4
3-7/8	2-1/2	1-7/8
4-1/8	2-3/4	2
4-1/4	2-3/4	2
4-5/8	3	2-1/4
5	3-1/4	2-1/4



按螺栓、螺母的尺寸及强度等级，确定扳手使用最大扭矩，在处理具体联接时，应确认工程制造商的使用参数。



重要：上表列出的六角尺寸仅用于参考。在特定系统中的特别尺寸应单独检查。



重载套筒必须符合：
ISO2725, 1301174, DIN3129
DIN3121, ASME-B107.2/1995



选择扳手时请务必注意拆松扭矩